FIG.1




FIG.2




FIG.3

INSTRUCTION STEP OPERATIONAL BLOCK LOCATION HEAT RELEASE COEFFICIENT MOV AX BX (2, 3), (2, 4) 2 LD AX 2D (2, 2) 1 ADD AX 2E (3, 1), (3, 3) 3 ST AX 2F (4, 3) 1		40		42	. 44	
LD AX 2D (2, 2) 1 ADD AX 2E (3, 1), (3, 3) 3	INSTR	UCTION	STEP	OPERATIONAL BLOCK LOCATION	HEAT RELEASE COEFFICIENT	
ADD AX 2E (3, 1), (3, 3) 3	MOV	AX	ВХ	(2, 3), (2, 4)	2	
	LD	AX	2D	(2, 2)	1	
ST AX 2F (4, 3) 1	ADD	AX	2E	(3, 1), (3, 3)	3	
	ST	AX	2F	(4, 3)	1	
					1	

<u>20</u>

FIG.4

<u>22</u>

- 3	0	1	0	1
2	1	5	0	2
0	0	0	4	1
1	0	0	0	0
2	4	0	0	1

FIG.5




FIG.6

